



The Marvin H.
SCHAEFER
Inspection Service, Inc.

800-345-2776 www.mhschaefer.com

HEAT PUMP

Most systems are split systems with an interior section containing a coil and blower, and an exterior section that appears exactly like any other air conditioner condenser unit. It is typically the exterior section that fails first. In years past, this exterior unit would be replaced if it failed and the interior unit would be left in place. It is not recommended that systems manufactured from 2006 onward be mixed with parts of systems manufactured prior to this time.

Typical heat pump replacement cost: \$3000 - \$5000

Actual prices can vary significantly depending on the contractor and area you live in. Obtaining at least three actual contractor prices is recommended before making decisions.